

Valley View Erosion Control

Fact Sheet

Organization Performing SEP	El Dorado County
Description of Work Performed, Other Details	The County also refers to this area as Tahoe Hills. Valley View drains to Meeks Bay Drive. The erosion control project involved installing curb and gutter, storm drain pipes, sediment basins, vegetation, rock lined ditches, rock slope protection, timber retaining walls, gabion retaining walls and removal of impervious surfaces. The primary focus of this erosion control project involved reducing the transport of eroding sediment from the project area.
SEP Status	Completed
Watershed in which SEP was performed:	Lake Tahoe
County in which SEP was performed:	El Dorado
Latitude of Project	39.0
Longitude of Project	120.1
Begin Date	n/a
End Date	12/9/1993
Project Budget	\$ 85,000.00
Water Quality Benefit or Objective	Water Quality Enhancement
Associated Enforcement Order	89-153
Enforcement Order Date	5/11/1989
Discharger Funding SEP	Fleur Du Lac Estates/Marina
Violation Leading to Enforcement Order	Illegal Dredging
Total Assessed Penalty	\$275,000.00
Number of SEPs Funded Under Enforcement	7
Lahontan RWQCB Staff Assigned to SEP Oversight	Lauri Kemper